


ORDER 9875878

\*\*\*\*\*

UNPLANNED MAINT. <InternalOrderSettlem.>



BUS2007-000009875878-PRD

Order	9875878	Ord.type	PM06	
Sup. Order		Act.type	P03	
Planning grp	H80	M.Plan		
Priority	1	Item		Main WC MECHAPSM
STATUS	REL ESTC GMPS NMAT PRC SETC			
Description	BORD. STAB. CLEAN Y-STRAINERS			

DUE DATE 11/26/2013

Func. Loc.	HZ-T0-EGF-A069254	Location
	BORDOVSKY STABILIZER	Room
	OCC/TRRC Number	
	Field Name	
	Meter ID Number	
Equipment		Cost Center A069254
		ABC ind.
	Begin Guarantee	
	Warranty End	

Sort Field  
 Manufacturer :  
 Manuf. Serial no:  
 Model no :  
 Technical ID no:  
 Size/Dimension :

### Operation list

Op	Sub	Description	Workcenter
		BORD. STAB. CLEAN Y-STRAINERS	
		11/26/2013 10:25:47 Cromwell Campbell III (CROMWC) Phone 1 281-552-6760	
		Need to clean the y-strainers on P-10507, P-10508, and P-10508. They have a high DP and are not sending as much flow as they should. Need it fixed ASAP.	
0010		BORD. STAB. CLEAN Y-STRAINERS	MECHAPSM
		BORD. STAB. CLEAN Y-STRAINERS	
		Need to clean the y-strainers on P-10507, P-10508, and P-10508. They have a high DP and are not sending as much flow as they should. Need it fixed ASAP.	
0020		(DITROL) LABOR	MECHAPSM
0030		(DLS) LABOR	MECHAPSM
0040		(PAC) LABOR	MECHAPSM